










**K154УД1****K154УД2 K154УД3**




$C = 30/K$   
при  $K_U > 10$   $C_1 = 3$  пФ


**K284УД1****K544УД1****K544УД2****K551УД1**

### К574УД1





$K_U$	-1	$\pm 10$	$\pm 100$
$R_1 R_2$ кОм	1,2	1,2	1,2
$C_1 C_2$ пФ	270	270	270
$C_3$ пФ	30	24	10









**К140УД9**




**К140УД10**



**К140УД11**



**К140УД12**



$$R1 = \frac{2U_{M-0,7}}{I_{CM}}$$